



US Army Corps  
of Engineers  
Huntington District

# Notice to Navigation Interests

Date: 17 MAY 2004

Notice Number: 04-26

In Reply Refer to: CELRH-OR-TD 502 Eighth Street, Huntington, WV 25701-2070 Telephone: 304-399-5684

## SHOALING CONDITIONS


### WINFIELD LOCKS AND DAM

#### KANAWHA RIVER, MILE 31.1

Notice is given that shoaling conditions have been reported at Winfield Locks and Dam, Kanawha River, mile 31.1. Mariners are urged to avoid a point bar located 1,600 ft below the miter gates in the lower approach extending approximately 230 feet towards the navigation channel from the water's edge.

Mariners can expect approximately 8.0 feet of water at the edge of the navigation channel at 9.0 lower gage reading at Winfield Locks and Dam.

The drawing below shows the location of the shoal in regards to the lower guard wall:



An additional notice will be furnished containing dredging information for this site after the water levels recede.

ARLIE D. BISHOP  
Chief, Technical Support Branch